


# TW - CONVERTOR DE TEMPERATURA 4-20mA , UNIVERSAL

- AFISAJ DIGITAL
- INTRARE UNIVERSALA
- PROTECTIE 20,32mA



## PROGRAMARE

**1234** AFISARE TEMPERATURA



**P.Cod** PAROLA



**.0000** VALOARE DE FABRICA



**tYPE** INTRARE



**K** P , B , E , J , K , R , S , T



**dP** VIRGULA (DOAR PENTRU PT)



**0**



**Unit** UNITATE DE MASURA



**°C** °C , °F



**AnLo** VALOAREA CORESPUNZATOARE  
LA 4mA  
(MINIM INTERVAL DE MASURA)



**.0000**



**AnHi** VALOAREA CORESPUNZATOARE  
LA 20mA  
(MAXIM INTERVAL DE MASURA)



**9999**



**A - 2** REGLAJ FIN IESIRE  
ZERO ( MINIM )



**.0000**



**A - S** REGLAJ FIN IESIRE  
SPAN ( MAXIM )



**.0000**



**d - 2** REGLAJ FIN AFISAJ  
ZERO ( MINIM )



**.0000**



**d - S** REGLAJ FIN AFISAJ  
SPAN ( MAXIM )



**.0000**



**CodE** PAROLA



**.0000** VALOARE DE FABRICA



**1234** AFISARE TEMPERATURA